


CellDB  
total ca  
0  
N

JPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

2293



Port Aden.

19th December, 1956.

This is to Certify that I have

Surveyed the temporary repairs effected to the broken upper

section main mast of the Steel Twin Screw Steamer

"GUMHURYAT MISR", 7830 tons gross of Alexandria, whilst she

lay afloat at this port on the 17th December, 1956 and

and, that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all repairs

recommended by me have been completed to my satisfaction, and

that I have Recommended that she be continued as now

classed without fresh record of survey, subject to the main

mast upper section being repaired as necessary on the vessels

arrival at Suez and before the end of January, 1957 and, to

any outstanding requirements being dealt with as previously

recommended

being fit to carry dry and perishable cargoes.

W. P. Watson

W. P. Watson.


Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.) 50m,7,54

(MADE AND PRINTED IN ENGLAND.)



Lloyd's Register  
Foundation

008759-008764-0226