

COPY FOR LONDON OFFICE.
Lloyd's Register of Shipping.

Port St. John. N. B.,

April 13, 1923.

This is to Certify that I have

Surveyed the ~~temporary repairs to leaky shell plate rivets in~~
~~way of No. 1 double bottom tank of the Steel Screw Steamer~~
~~"BRANT COUNTY", 5289 tons gross of Bergen.~~

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and

that I have Recommended that she be ~~continued as now classed~~
~~* 100 A.1. subject to drydocking for further survey and repairs~~
~~at a convenient opportunity.~~

being fit to carry ~~cargo.~~

C. E. Dalton

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors or other Officers, or Agents of the Society."