

1

25 JUL 1947

Received from Chief Surveyors.....

Sent to Chief Surveyors.....

VESSEL'S NAME "EMPIRE JOAN" REPORT Lon. No. 115222

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey..... When due.....

The class is subject to set up bar keel and bottom plating in way of boiler stools (s.s.) being dealt with at the first convenient opportunity.

The Admiralty state in a letter dated 12.5.47 that this tug is now under the supervision of Dockyard Service and that the services of this Society are no longer required.

It is therefore submitted the class of this tug be withdrawn from the Register Book and 3 dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class.  
Insert (...)

WOT.

22.7.47.



© 2021

Lloyd's Register  
Foundation

008789-008795-0220