

# The Dover Harbour Board.

ALL COMMUNICATIONS  
TO BE ADDRESSED TO  
THE GENERAL MANAGER.

HARBOUR HOUSE,  
NEW BRIDGE.

TELEGRAMS:  
HARBOARD, DOVER.

TELEPHONE:  
DOVER 296.

RECEIVED DOVER.

- 3 FEB 1945 HB/6/338

ANSD...5-2-45.....

1st February, 1945.

The Principal Surveyor,  
Lloyds Register of Shipping,  
71 Fenchurch Street,  
LONDON, E.C.3.

Dear Sirs,

*Boothman 1262*

TUG "EMPIRE JOAN".  
-----

In order to alleviate the unsatisfactory conditions that have been experienced in the Crew's quarters, lower forward accommodation, on the above craft, due to heavy condensation and poor ventilation, arrangements were recently completed with the Ministry of War Transport for the ship's side and forward bulkhead to be lined with plywood fastened and strapped to allow for quick removal for giving access to side of ship and bulkhead plating.

The decking has been treated with Durastic Combination Asphaltic flooring to 1" thickness with boundary fillet.

This work is now in hand and will be completed by Monday next 5th February, 1945, the vessel being returned to service on 6th February, 1945.

A copy of Drawing No. G.190 is enclosed showing this work, ~~done~~.

Yours faithfully

*J. W. Smith*  
HARBOUR ENGINEER.

Encl:

© 2021  
Lloyd's Register  
Foundation  
008789-008795-0228

Referred to the Chief Ship Surveyor.

1936

3 FEB 1945

Handwritten initials and signatures, including 'H.S.' and 'H.P.'.

Dear Sir,  
Reference is made to the letter of the 15th inst. in which you requested information regarding the status of the ship 'H.M.S. ...'.

The ship 'H.M.S. ...' is at present in the possession of the Admiralty and is being used for the purpose of ...

Yours faithfully,  
The Chief Ship Surveyor.

MC ...

Dear Sir,



Lloyd's Register Foundation

1945

RECEIVED

NEW BRIDGE  
HARBOR HOUSE

DOVES 308  
LETTERS  
HARBOR HOUSE

1945