

Particulars of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides the replacement of the

of the Ship's
least p

LLOYD'S REGISTER OF SHIPPING,

425 KING STREET

JACKSONVILLE, FLA.

10th January 1920.

The Surveyors,
Liverpool.

Dear Sirs:-

The steamer "SALACIA" requested survey at Savannah, Ga., where ceiling was being laid in accordance with requirements for the carriage of oil fuel.

The ceiling is laid on top of 2" battens (athwartships) and is satisfactory.

Master desired you be advised.

Yours very truly,

J. Hugh Boyle
Surveyor.

79958.



© 2021

Lloyd's Register
Foundation

008796 - 008803 - 0019

Travelling Expenses (if chargeable) £

1920

Surveyor to Lloyd's

assigne
ow ve
his pu
bol
H
Car
red
B
e
d, b
m
ref
ing
ds
alin
B
de
m
to ob
or Y.M
ate if o
en put o
Yards,
on, how
to if w
tent let
s, No. c
(State
ength
(on t
Rule len
& We
ng & Ru

he Reg
as cla

19
in

Surveyor to Lloyd's

