

nm. Horse Power as per Rule 90.

Is Refrigerating Machinery fitted for cargo purposes

Is Electric Light

1 E

ved by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME *Freshwater* REPORT *Liv.* No. *119301*

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

*Triple Expansion.*

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }  
approved type

*Yes*  
*No*  
*Yes*

This vessel's machinery appears to have been built in accordance  
with the Rules and the approved plans, *& Admiralty Modification*, and it is submitted she is  
eligible to be classed *+LMC 3.43.*

*L.H.*  
*19/4/43.*



© 2021

Lloyd's Register  
Foundation

008823 - 008830 - 0020

*main bearing + connecting rod bolts.*