



Reference:  
Classn. (S) .....

RECEIVED  
OCT 1957  
LLOYD'S REGISTER OF SHIPPING  
UNITED WITH THE BRITISH CORPORATION REGISTER  
Ans'd

Hamburg 1, Mönckebergstraße 27

Telegrams: Surveyors, Hamburg  
3071/PGR/L

Telephone: No. 33 10 25 (5 lines)

7th October, 1957.

Dear Sir,

# EDWARD DEMBOWSKI "  
Hamburg Report No. 5849.

With reference to your classing letter dated the 24th September, 1957 we have to inform you that no drawings have been prepared for the fitting of the doubling plates on shelterdeck.


The position of the doubling plates p&s are as given in our report No. 5849.

Lengths between frames Nos.  $37\frac{1}{2}$  and  $122\frac{1}{2}$

Breadth 40.25"

Thickness .60"

Sketch of Position



The Secretary,  
London

Yours faithfully,  
The Surveyors  
Per: *[Signature]*



SR

CLASSIFICATION

H <sup>mg</sup>  
R. a. f.

<sup>14</sup>/<sub>10</sub>  
6 B 257.

v/s. N. 03. 30/8. Temp. R. 14.  
Ham. 4/10. Ram. H.



© 2021

Lloyd's Register  
Foundation