

F.E.

Received by Chief Ship Surveyor

11/1/12

Received from Chief Ship Surveyor

VESSEL'S NAME

At St. Johns Dock No 3

Rpt.

Mab

No.

7174

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

21.84

Depth "d"

7.0

Framing: Table No.

3 page 9

Description

Angle angle, as approved

Longitudinal No.

1310

Proportions


Length


Depth

7.68

~~Deck~~ Sheerstrake

30 in lieu of 24 as required by
lowest grade of rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100 A-1. (Stub) For towing purposes as recommended

 100 A-1. (Stub) For towing purposes
1 str (etc)

DTF 7 3L FPT 5L

BK 6'. 3BH Cmn. dregds at 60



© 2021

Lloyd's Register
Foundation