


hyk 1

83460 being converted to closed
sheller deck ~~purpose~~ deeper loading
slot As dim one of owners letter 19.8
to master conflict latest instruction
regarding closing between decks this
please discuss with Lambert Bros &
cable instruction and new job





J

2/12/42

Lloyd's Register
Foundation

008917.008924.0123

008917.008924.0124