

WOKINGHAM COPY.

28th July, 1942.

Dear Sirs,

With reference to your reports Nos. 51664 and 51665 on the Tugs "EMPIRE FAIRY" and "EMPIRE GOBLIN" respectively, I have to request you will be good enough to let me know whether the combustion chamber bottom plating in these cases is 25/32"; also if the combustion chamber wrapper plate seams were butt welded. At the same time I shall be glad to receive, for record purposes, details of the methods adopted for the heat treatment of the combustion chambers after welding.

I have also to request you will be good enough to forward for reference the approved Pumping Arrangement plan and may say that this plan will be returned to you without delay.

I am, Dear Sirs,
Yours faithfully,

pro Secretary.

The Surveyors,

HULL.

© 2020

Lloyd's Register
Foundation