

"EMPIRE FAIRY"Hul. First Entry Report
No. 51664.

It is submitted before this case receives the consideration of the Committee, the Surveyors' attention should be directed to the requirements of Section 32, Clause 1 of the Rules and requested to state why cement or other approved covering on the bottom has not been fitted.

It should be added that the requirements of the Rules are specific and, if it was proposed to depart therefrom, the matter should have been submitted for consideration.

*Confirm whether plating is
joggled as stated in
p. 2 of the report - or
ordinary as shown in
the approved plans*



23.7.42.

Lloyd's Register
Foundation