

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

20 APR 1960

GB
 SHIP'S NAME "GUNTUR" REPORT Sng. No. 13876

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

SPECIAL SURVEY (C) becomes due 11,60.

The SINGAPORE Surveyors report (3,60), ship examined in dry dock and the requirements of an Annual Survey complied with.

In accordance with Circular No.2106 and at the Owners' request this ship has been generally examined and the thicknesses of shell, decks and internal structure as ascertained by drilling are embodied in this report and on separate plan attached to this report.

On account of wear and tear, repairs effected to Nos. 1,2 & 3 tank longitudinal bulkheads.

IT IS SUBMITTED record of 'DS 3,60' be assigned as recommended.

DS 3,60.

IT IS FURTHER SUBMITTED this report be sent to Ship Research Department for consideration of shell and deck thicknesses in order that the Owners may be advised of the extent of anticipated repairs for the Special Survey.

ENGR. SURVEYORS TO NOTE.

DS
11-4-60



© 2021

Lloyd's Register
 Foundation

008473-008481-0221