

COPY.

Lloyd's Register of Shipping.



Port Kobe.

20th December, 1940.

This is to Certify that I have

Surveyed the ^{Donkey}Boiler and ^{Part of the}Machinery of the **STEEL SINGLE SCREW**
MOTORSHIP **"SYDNEY MARU"**,

5425 tons gross, of Osaka,

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have
Recommended that the record of **L.M.C. (G.S.) 1, 39.**
with fresh under date **12. 40.** and **D.B.S. 12. 40.**

be made in the Register Book in the case of this vessel.

(P.T.O.).

K. Paredaya

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

COPY

(2)

M.S. "SYDNEY MARU",

Kobe, 20th December, 1940.

PARTS NOW EXAMINED for Part LMC(CS) :-

MAIN ENGINE:-

Nos. 2 & 5 cylinders, pistons, valves, gears & covers.

Nos. 2 & 5 connecting rods and top ends.

No. 2 bottom end.

Nos. 1, 2, 3 & 6 crankshaft journals.

Thrust shaft.

AUXILIARIES:-

No. 3 (Port) Auxiliary Diesel Engine:-

All working parts - complete.

No. 2 (Port Aft) air compressor - all working parts - complete.

Bilge and Sanitary (Independent) pumps.

No. 1 (Inboard) Jacket cooling water pump.

No. 1 (Inboard) Piston-Lubricating oil combined pump.


General service pump.

Sea valves and cocks.

Propeller and outside fastenings.

-----000-----

K. Pakedaya
Surveyor to Lloyd's Register.



© 2021

Lloyd's Register
Foundation

212
008473-008481-0249