


JUN 1949

"T E M A R A"

Provided the structure in all cargo tanks be specially examined at the next dry docking, and all defective material is dealt with as recommended by the IAGOS Surveyor, and the vessel is made efficient until the due date of the Special Survey, the Owners' request to re-drill the plating <sup>in</sup> ~~until~~ January 1951 is submitted for favourable consideration.



© 2020

Lloyd's Register  
Foundation

SA 31/5/49  
B.M.

009993-009003-0353