


Barge "HOOKE".

This vessel became due for 2nd.Special Survey No.3 in September 1937, and the greater part has been held.

To complete the same, repairs are required to shell plating, framing, bulkheads, stringers, deck beams, hatch coamings, beams and rigging at the completion of the Special Survey.

The year of grace having expired, the Owners, recently furnished the usual undertaking.

The Hull Office have telephoned this morning to say that the Owners' Superintendent states they have an urgent offer for one or two cargoes between Immingham and Selby, and as this is in river service, and not open sea, the Owners are making application for the Committee's permission to undertake this work which, it is estimated, would occupy her say until the end of the year.



Submitted for consideration,
whether in view of the proposed
restriction might be in service, the Owners
request be acceded to.
H. 11. 38.



© 2020

Lloyd's Register
Foundation