

Rpt. 14.

Port of **MULL.**

7th July, 1938.

## REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs,

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the  
Name of Vessel) **Lighter "MOOKE",**  
on the (Date of examination) **6th July,** 19 **38,**  
I have to report that I found **Foremast.** Pole (wood) mast and steel  
latchet both in good condition. No mast wedges. Fore stay and  
starboard shrouds to renew. Rigging screws and shackles to take  
off and anneal. Port shrouds and rigging screws in good condition.  
Lug sail and spar in good condition.  
**Mainmast.** Pole (wood) mast in good condition. No mast wedges.  
Steel latchet front plate and angle on starboard side to renew.  
Shrouds port and starboard and backstay and rigging screws all  
in good condition. Staysail in good condition.

Fee £ : 10 : -

To the Surveyors,  
Lloyd's Register of Shipping,

**MULL.**

2m,3.34.

William Broughton



© 2020

Lloyd's Register  
Foundation

009015-009020-0110