

30 JUN 1939

2 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "RISKATO".

Rpt.

Gms.

No. 20987.

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ~~ENGINES AND~~ BOILERS ~~FOR S.S.~~ No.

This Survey, due 6,39 now ~~partly~~ held; screw shaft examined. ~~now~~  
~~completed~~, and the following repairs carried out (due to wear and tear):-

A furnace renewed and minor repairs.

It is submitted the vessel is eligible to remain as classed, with  
 notation of BS 6,39, S 6,39 as recommended.



© 2021

Lloyd's Register  
 Foundation

28.6.39.

009021-009029-0015