

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report.....10..... When handed in at Local Office.....19..... Port of London

No. in Survey held at..... Date, First Survey..... Last Survey..... 19.....
Reg. Book..... (No. of Visits.....)

75401 on the Wood, Iron or Steel TS. Steamer 'Hakusan Maru' YEAR. MONTH.
TONNAGE:- Built at Nagasaki By whom Mitsubishi Iron Works When 1923 9
GROSS 10380 Owners Nippon Yusen K.K. Owners' Address.....
UNDER DK 9390 Managers..... Port belonging to Tokyo
NET 6271

Surveyed Afloat or in Dry Dock? Name of Dock..... Destined Voyage.....

Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 6978 Port Yha

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month..... Year.....
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
„ „ in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	„ length..... mean diam. (on board)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	„ Rule length..... size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		„ „ at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as classed in the Register Book without ‘fresh record of Survey,’” “to remain as classed and to have record of survey, 1,38,” or “to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38.”

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of Shipping.


Committee's Minute

Character Assigned

TUE. 28 JAN 1941

Onit class on
reprint of Reg. HK

Class omitted
from



Lloyd's Register
Foundation