

2 - OCT 1933

s. s. "PENNERF".

London 99189a.

IR,

The examination of the screwshaft became due 8,33.

From information received through the Nantes Surveyor the Owners state that the vessel is not classed with this Society and they further state that the vessel was classed with the Bureau Veritas three years ago.

In the circumstances no action is being taken by them in regard to the screwshaft survey.

It is submitted the vessels' class be expunged from the Register Book, and three dots (...) be inserted in lieu, indicating withdrawal of class at Owners' request,

*See Owners  
Loy + Co  
with min*


Withdraw class.

Insert ...

*L.L.*  
*[Signature]*

29.9.33.

*[Signature]*



© 2021

Lloyd's Register  
Foundation