

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

ESSEL'S NAME AURANIA Rpt. Got No. 13078

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The GOTHENBURG Surveyors report the vessel placed in dry dock, bottom coated, and on account of damage (cause not stated), a shell plate repaired by electric welding.

It is submitted the vessel is worthy to remain as classed with record of survey 10.40.

100A1  
10.40 Got.

*BAH*

8/8/41



The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be entered in the Register Book.



© 2021

Lloyd's Register  
Foundation

009058-009066-0148

found efficient?

No.

Transoms Pointers, & Crutches ditto

Cables (S)