

NEWFOUNDLAND DOCKYARD

Form 797

St. John's, N.F., October 22nd, 19 35.SPECIFICATION OF REPAIRSS.S. "DAISY"G.T.R. - 248 -

Port of Registry

STRANDING	DAMAGE	ST.	MARGARETS	BAY
		BELLE	ISLE	STRAITS

Stem Bar at Forefoot Twisted and badly scored.

Damaged section to be cut out and Renewed.

PORT SIDE

A 1 Buckled and Fractured To be renewed.

STARBOARD SIDE

A 1 Buckled and Fractured. To be renewed.

B 1 To be removed for access to scarp of Stem Bar and reriveted.

All loose and broken cement to be cut out and renewed.

All removals for access to repairs to be replaced.

NEWFOUNDLAND DOCKYARD*R. Thompson*CLASSIFICATION SURVEYOR*D.M. Macfarlane*UNDERWRITERS SURVEYOR*D.M. Macfarlane*OWNERS REPRESENTATIVE*John Pollock*

© 2021

Lloyd's Register
Foundation

009058-009066-0229