

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

Enclosure.

24th June, 1921.

Dear Sirs,

With reference to your First Entry Report No.6025 on the S.S."WRAY CASTLE" ex "PARIA" I shall be glad if you will be good enough to state whether the particulars given in the report regarding the frame spacing in the peaks, width and thickness of the upper deck stringer plate, size of propeller post and riveting in the butts of the outside plating are correct.

You should also state the number and particulars of the side stringers, size of upper deck stringer angle, if two web frames are fitted forward as shown on the plans, whether the butts of the upper deck stringer plate are quadruple riveted for half length in the wells, particulars of the steam and hand steering gear, the length of the erections, length and capacities of the double bottom and peak tanks and the other particulars required on page 4 of the report.

At the same time you should endeavour to ascertain the type of stockless anchors on board and where the anchors and chain cables were tested.

© 2021
Lloyd's Register
Foundation

009067-009073-0343 1/2

COPY.

Your report is returned herewith for correction
as necessary.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

FALMOUTH.



© 2021

Lloyd's Register
Foundation

0343 ²/₂