

1

Sent to Chief Surveyors

13/8/10

Received from Chief Surveyors

VESSEL'S NAME

Lt J. S. Snaresell

Report

LW

No

64588

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.02.)

Nature of Survey

First entry

When due

+ A.1 (Steel) Shutter deck with grubboard
For Service in the Irish Channel

2 Bk (u-ps Lt) + Shutter deck

NB: 6m DBa 32 u 6.34 f 58 148 FPT 106 APT 356

FR 7BH. 6m. Lloyds at 6 P.

MR

RBF
15/8/10

It should be pointed out to the Liverpool Surveyors that the class which should have been assigned to this vessel is + A.1 (Steel) Shutter deck with grubboard, For Service in the Irish Channel.