

18 SEP 1941

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME..... HAVANA MARU..... Rpt. Kob No. 11847

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

The KOBE Surveyors report the vessel placed in dry dock, bottom coated, and on account of collision renewals and repairs effected to some shell and deck plating, frames and beams.

Minor repairs effected.

Repairs effected due to wear and tear to rudder, beams in deep tank; and 4 shell plates and 2 deck plates renewed.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.41.

100A1

6,41 Osa.



© 2020

Lloyd's Register
Foundation

009122-009130-0067