

TELEPHONE: SEYMOUR 2022

TELEGRAPHIC ADDRESS:  
"REGISTER" VANCOUVER  
CODE: A B C 5TH EDITION**Lloyd's Register of Shipping**BRITISH COLUMBIA  
LONDON.

RECEIVED NOV 20 1918

ANSR

VANCOUVER, B. C., October 21st. 1918.

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
London, E. C.


Dear Sir:-

With reference to your letter of September 17th. ult., re webs in Nos. 1, 2, 4, and 5 hatchways in the First Entry Report of the S. S. "ALASKA" and my letter of October 8th in which I stated that the figure 5 in the First Entry Report was a clerical error, and that 6 hatch webs were fitted.

I regret to say that I have made a mistake in that statement, as since writing you on October 8th. I have looked over my note book, and find that there were only 5 webs, as stated in the First Entry Report, and not 6 as shown on the profile .

At the time of answering your letter of September 17th. I looked over the profile which shows 6 webs, and took it for granted that I had made a clerical error in the First Entry Report, and wrote you to that effect, finding afterwards that I had been incorrect.

The 5 webs have been suitably increased in strength



© 2020

Lloyd's Register  
Foundation

009139-009143-0071 1/2

0071 1/2



-2-

to rule requirements and are also fitted in vessels No. 2 and  
3. In vessels 4 to 10 these five webs are shown on approved plans.

I Remain,

Dear Sir,

Yours faithfully,

JL/JH.

*Jas Lunney*



© 2020

Lloyd's Register  
Foundation

0071 2/2



Referred to the Chief Ship Surveyor.

*C.S.S.*  
NOV 20 1818

Also for Mr. S. A. Hill to note.

*M*  
20 11.18

*For  
Hill  
to  
note*



© 2020  
Lloyd's Register  
Foundation