

"Examined L.R. 1.47".

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME "EMPIRE CONSEQUENCE" REPORT Phl. No. 8947

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Equipment. ~~When due~~

75 fathoms of chain cable require to be supplied at first opportunity.

Had this case been dealt with in this Office ACTION would have been DEFERRED for equipment.

ADM.  
20.5.47.



© 2020

Lloyd's Register  
Foundation

009139-009143-0144