

TELEGRAMS: REGISTER, GLASGOW.

TELEPHONE: CENTRAL 6491 (4 LINES).



Lloyd's Register of Shipping,

RECEIVED
1 OCT 1950

95, Bothwell Street, GLASGOW, C.2.

3rd October, 1950.

Dear Sir,

S.

M.S. "ERLING BORTHEN"

In reply to your letter of the 27th ultimo regarding Greenock Machinery First Entry Report No. 24194 on the above vessel, I beg to acquaint you that the Surveyor confirms that the pitch of the rivets in the longitudinal seam of the Donkey Boilers is $7.1/8$ " as approved.

The error on the report is due to the pitch given in the riveting table on the plan being 7" and not $7.1/8$ ", which is correct. I shall be glad if you will kindly arrange for the plan and report to be amended accordingly.

Yours faithfully,

The Secretary,
LONDON.



Secretary to the
Scottish Committee.

Lloyd's Register
Foundation

009139-009143-0230

Referred to the D.O.
Referred to Mr. Perxis.

u/s Cal 8/9
Int cont (4)
[Handwritten signature]

For Engineer Surveyors (F.E. Rpts) to note
Notes
Sub 5/10/50



© 2020

Lloyd's Register
Foundation

[Faint, mirrored text from the reverse side of the page, likely bleed-through from another document.]