

Volsella.

F.E.

Received by Chief Ship Surveyor 22.10.06

Received from Chief Ship Surveyor

VESSEL'S NAME *See S. S. Verastom*

Rpt. *Kpl.* No. 13097

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>2/20"</i>	<i>Proportions</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Deep (Bulb angle) framing, 1/2" less in depth, (viz., ordinary, deep, zed, channel or bulb-angle). but augmented by 1/20" increase in thickness.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *† 100 A 1 ("Steel")* as recommended.

† 100 A 1 ("Steel")

1 DR (2m) & deep framing

M. B = Cell DB a 4 u E 104' f 122' 530 E APT 30 E

FK 48H Cam. Ploy's A4EP P21' B74' F30'



C. H. J. 22/10/06

Lloyd's Register Foundation

009152-009160-0091