

21 FEB 1941

11

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *GENZAN MARU* Rpt. *Sub* No. *2614*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.

Survey

The *Shimonoseki* Surveyors report this vessel placed in dry dock, bottom cleaned and coated, ^{a shell plate renewed} repairs or renewals to *tank tops and margins* and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey *12.40* as recommended.

*100 A1
Spec DR.
12.40 Sub.*



© 2021 *[Signature]*
Lloyd's Register
Foundation
10.2.41

009161-009169-0098