

54.84

erd. Thomsen *Enclosure*
Bremerhaven.

Bremerhaven, *1st November* 1906

The Secretary
of Lloyd's Register of British and Foreign Shipping
LLOYDS REGISTER
LONDON.
London.

Sir!

REC'D 3 NOV 1906

10/32

In your Freeboard letter on the S. S. Rotensfel
you expressed the request that the Under deck tonnage has to be
verified and I am very sorry to say that the Under deck tonnage of 5200 tons
as given to me by the builders is not correct, by official measurement it is
5326 tons.

Therefore the coefficient of fineness is 80 instead of 78 and the
Freeboard will be 6' 9" instead of 6' 7½".

I beg to enclose your Report which you were so kind as to send
for my information and have marked the amendments which in my opinion
will have to be made in pencil on it.

Please to examine the same and kindly let me know whether I am
now correct.

I remain Sir

Your obedient Servant.

F. Thomsen

Surveyor to Lloyd's Register.



© 2021

Lloyd's Register
Foundation

009161-009169-0115

Fresh Water Line

above centre of Disc

Indian Summer Line

" " "

Amended Tables
1906.

State for India is Council.

Referred to the Chief Ship Surveyor.

ad
NOV -3 1906

For Mr. White
& Mr. Manley.

G.M.



© 2021

Lloyd's Register
Foundation