

LLOYD'S REGISTER OF SHIPPING,

17 BATTERY PLACE,

LLOYD'S REGISTER, NEW YORK September 13th, 1923.
LONDON.

REC'D 24 SEP 1923

ANSW _____

H.

Dear Sir:-

S.S. "CHIPPEWA"

On receipt of your letter of the 3rd ultimo I immediately communicated with the Society's Surveyor at Cleveland who now informs me he has been in communication with the Owners and has made arrangements for the main engines to be examined under working conditions and the safety valves to be adjusted under steam next time the vessel is in the district.

The Owners further informed him that oil burners had been taken out and the vessel is now burning coal entirely.

No arrangements can meantime be made for the survey of the tail shaft, but I have asked Mr. Drummond to endeavor to have this done before the opening of navigation next year.

I am, Dear Sir,

Yours faithfully,

J.P. Davies
Secretary to the
American Committee.

The Secretary,
LONDON.

ACJ/AB



© 2021

Lloyd's Register
Foundation

069243 - 009255 - 0066

Referred to Mr. S. A. Hill

BA/DA

LONDON.
The Secretary.

24 SEP 1923

American Committee.
Secretariat to the

London Registry.

I am, Dear Sir,


before the opening of navigation next year.
I am glad that I have asked Mr. Johnson to endeavor to have this done
No arrangements can meantime be made for the arrival of the

before that and the vessel is now running over England.

The Council further informed you that all matters have been
the vessel is in the district.

conditions and the safety valves to be repaired under steam next time
have arrangements for the main engines to be examined under working
now inform me to be put in communication with the Council and has
secretary committee with the Society, a copy of the letter of the 27th ultimo I in-

Dear Sir:-



THE SECRETARY

© 2021
Lloyd's Register
Foundation

September 1923

LLOYD'S REGISTER

LONDON

11 BATTERY PLACE

LLOYD'S REGISTER OF SHIPPING

REGISTRATION
LONDON