

S.S. "BOMBARDIER".

It is submitted the Owner of this vessel should be informed that the Society's Surveyors at Sunderland state that in their opinion the amount of the work carried out on this vessel when she was converted to cargo carrying purposes last year and classed with this Society was sufficient to render her eligible for the notation of "S.S.No.3-8,20".

Further, if such a record were assigned to the ship, the Special Survey No. 1 would then become due four years after the date assigned for the Special Survey No. 3, i.e. not until August 1924.

In these circumstances, it is assumed that the Owner would be desirous of having the notation of "S.S.No.3-8,20" made against the vessel's name in the Register Book, but he should be requested to confirm this.

ARSL *[Signature]*

27.10.21



© 2020

Lloyd's Register
Foundation

009256 - 009266 - 0268