

CONFIRMATION OF LETTER

Lloyd's Register of Shipping

71, Renschurch Street, E.C.

8th August, 1918.

Dear Sirs,

M.

With reference to your First Entry Report No. 3950 on the Twin Screw Motor Ship "BULLAREN", built by Messrs. Aktiebolaget Gotaverken, I have to request that you will state whether double butt straps are fitted to the keel plate for 3/5ths amidships as required, and also whether the butts to the upper deck stringer are treble-riveted.

Will you also please state the name of the works at which the tensile and breaking tests were applied to the anchors and chains at Dusseldorf.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

GOTHENBURG.



© 2021

Lloyd's Register
Foundation

009278-009286-0023

Bulb Angle, Plate, Tee Bulb or Channel

180 75 105 180 75 105

Deck.* Material and thickness

Third, Fourth & Fifth Deck Stringer Plate,)