


Name of Vessel

S.S. "Bullaren"

No. in Register Book

	FEET.	INCHES.
Moulded Depth	30	0
Stringer Plate		$\frac{1}{2}$
Thickness of wood sheathing if required		-
Statutory deck line above intersection of <u>actual</u> deck at side		$1\frac{3}{4}$
Total depth from top of statutory deck line to top of keel	30	$2\frac{1}{4}$
Freeboard recorded	4	$3\frac{1}{2}$
Moulded Draft	25	$10\frac{3}{4}$
Add for keel—Flat or Bar		$2\frac{1}{8}$
Draught	26	$0\frac{7}{8}$
Draught for record	26	



© 2021

Lloyd's Register Foundation

Ship  
ding percentage

3.04 =  $\frac{1}{2}$  diff  
421.96

Summer