

1

Sent to Chief Surveyors _____

Received from Chief Surveyors 28 AUG 1925VESSEL'S NAME Stl. Sc. "DALMORE".Report Lon.No. 89227 A**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/92.)

Nature of Survey _____

When due _____

The s.s. No.1 became due 3-25.

In reply to an enquiry a letter has been received from the Owners in which they state "the above tug is now doing harbour duty in Penang and it is not considered necessary by the Owners to keep "the vessel in class".

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class.

Insert ...

W.S.
J.W.D. C.M.S.
 28.8.25. © 2020
 Lloyd's Register
 Foundation