

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME Steel S.S. "DALMORE" Rpt. Lth. No. 15781

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_

First Entry.

This vessel after being wrecked at Leith has been dismantled for shipment to Singapore where she will be reerected and finished complete. In addition to testing the decks etc on completion, the hand pumps also require to be tested.

The Singapore Surveyor should be advised & requested to forward a report on form 8 when the work has been completed to his satisfaction.

Copies of the approved plans should be forwarded to the Singapore Surveyor for his guidance.

R. 15/7/20



© 2020

15-7-20

Lloyd's Register Foundation