

Lloyd's Register of Shipping

224.

10, Trafalgar Road, London

To Chief Surveyors _____

Received from Chief Surveyors 17 JUL 1928

SEL'S NAME twin sc. "THE 60-TON CRANE". Report London. No. 92854a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Kind of Survey Boiler Survey When due 6.28

In reply to enquiries made regarding the boiler survey, The Owners write to say that it has been decided not to continue the classification in the Register Book.

IT IS SUBMITTED the class be withdrawn and three dots inserted, indicating withdrawal of class at Owners' request.

APR 18.7.28.

Lloyd's Register Foundation

Withdraw class.
Insert (...).

009341.009349-0074