

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

20th October, 1926.

Dear Sir,

Reverting to your letter of the 6th and my reply of the 7th ultimo respecting your Steamer "2BULLA", I beg to acquaint you that the Committee have now had before them reports received from the Society's Surveyors at Falmouth of an examination made of the furnaces of the main boilers of this vessel.

The Surveyors recommend that the furnaces of the starboard boiler should be repaired before the vessel proceeds to sea, and that the furnaces of the centre and port boilers should be examined and those of the starboard boiler renewed within six months from the date of resuming service, and I have to say that, in the circumstances, the Committee have continued the vessel's class subject to this being done and to the Second Special Survey No. 2 being completed before the expiration of the year of grace in April next.

I am, Dear Sir,
Yours faithfully,

General Manager,
Australian Commonwealth
Line of Steamers,
Australia House,
STRAID, W.C.2.



© 2021

Secretary.
Lloyd's Register
Foundation

009341 - 009349 - 0254