

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

This Donkey Boiler has been built under special survey and the materials and workmanship are good. When completed it was subjected to the tests prescribed by the Rules and found tight and sound.

For recommendations, see foregoing sheet.

Certificate (if required) to be sent to

The amount of Entry Fee... £	:	:	When applied for,
Special £	:	:	25/12/1907
Donkey Boiler Fee ... £	:	:	When received,
Travelling Expenses (if any) £	:	:	27/12/1907

Wm R. Austin
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute **Glasgow 30 DEC 1907**

Assigned

See attached reports

[Handwritten signature]



© 2021

Lloyd's Register Foundation