

proposed. Under the circumstances the boiler safety valves

not been adjusted and the owners have been informed that

Sept 1.1 8

the record

				Screw Shaft		
				Rule Size	Fitted	
diam	propeller	Screw Shaft	2 liners	151.9 ^m / _m	163	
"	"	"	" 2 liners	163 ^m / _m		
"	"	"	" 1 liner	155 ^m / _m		



© 2021

Lloyd's Register
Foundation

009376-009386-0043

The Secretary,

TRIESTE

the
by the Italian Government on the
certificate of the Registro Navale
but they will reduce the size
the propeller at the first opportunity
+ later fit a screw shaft with a
continuous liner and also a more
suitable propeller.

It is submitted action be de

~~If the rules for the propeller now fitted~~
~~+ the original working pressure of 170 lbs~~
~~a screw shaft 155 mm diam + fitted with~~
~~continuous liner would be required~~