

COPY

Lloyd's Register of Shipping.



Port Kobe.

13th June, 1941.

This is to Certify that

M. Kamakura,

the undersigned Surveyor to this Society did at the request of the Owners, attend on board the

M.S. "COLUMBIA MARU",

5618 tons gross, of Tokyo,

on the 13th June, 1941, whilst the vessel lay, afloat, in Osaka Harbour, for the purpose of examining the Anchors, Chain Cables, Windlass, and other Mooring Gear, prior to the vessel's departure for Christmas Island, to load cargo.

The port and starboard bower anchors, the spare bower anchor, and the stream anchor were examined, found in good condition, and in accordance with the Society's requirements.

The vessel is equipped with 270 fathoms of 2½" stud link chain cable in accordance with the Society's requirements, 135 fathoms in each hawse pipe. This Chain Cable was examined and found in satisfactory condition. The steel wire, towline, and hawsers and warps were also found to be in satisfactory condition.

The electric driven windlass was examined under working condition while the port and starboard cables were being hove in, both separately and simultaneously, and found to be in satisfactory working condition. The cable lifters, brakes, and stoppers were examined and found in good order.

(continued).

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

COPY

(2 -)

M.S. "COLUMBIA MARU",

Kobe, 13th June, 1941.

last

Periodical
complete
extent of
should be
examined
reported

The electric mooring winch, aft, with its warping
ends was examined and found in good working order.

As a result of the foregoing examination the under-
signed is of opinion that the Anchors, Chain Cables, Windlass,
and other Mooring Gear, are now in satisfactory working order,
and condition.

HOW
were

the S
in sa
in sa

starch
saw

SUMMARY

Rever
Rever
Fair

PRESENT

Deck
Caulking of
Gunnings
Bower & P
Outside Iron

Bracehook

Transoms

Frames

Reverse Frame

Longitudinal

Transverse

Floors

Kellogg

Stringers

Inner Bottom

General

this
surve

neg

M. Law abua
Surveyor to Lloyd's Register.



© 2021

Lloyd's Register
Foundation

009409-009417-0259 2/2