

5m,6,14

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

29 JAN 1927

VESSEL'S NAME

S.S. "RANGITOTO"

Report London

No.90902A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Boiler Survey

When due

12.26

The Boiler Survey became due at the end of December last.

The Auckland Surveyors states he has received an intimation from the Owners that they desire the vessel's classification to be withdrawn.

It is submitted the vessel's class be withdrawn from the Register Book and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

28.1.27.



© 2020

Lloyd's Register
Foundation

009418-009427-0275