

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

Enclosure.

17th February, 1927.

H. Dear Sirs,

With reference to the classification in this Society's Register Book of the steamer "COMBO", I beg to acquaint you that this vessel's boiler became due for survey in September last and the screwshaft in December, and the Owners have informed the Society's Surveyors at Bordeaux that they have given instructions to their Representatives at Bathurst to make arrangements for carrying out the inspections as soon as possible at that port, where the vessel is always in service.

As you are doubtless aware the Society has no Surveyor stationed in the vicinity of Bathurst, and in the circumstances the Committee will be much obliged if you will appoint a competent and independent surveyor to carry out the inspections upon your receiving a request from the Owners, or their Representatives, to do so.

A form for reporting the surveys is enclosed herewith which should be returned to this Office in due course, and I may say that the survey of the boiler should

© 2021

Lloyd's Register
Foundation

009428-009439-0101 1/2

S.S. "COMBO".

COPY.

Lloyd's² Register of Shipping.

include a thorough examination both internally and externally together with the mountings and safety valves and the adjustment of the latter under steam to a safe working pressure not exceeding 180lbs. per square inch.

71, Fenchurch Street, E.C. 3.

I have to say that the Committee rely upon your satisfying yourselves of the integrity and professional ability and experience of the Surveyor selected for this purpose, and they will be much obliged if you will kindly impress upon the Surveyor the necessity of exercising the greatest care to see that the Society's requirements are satisfactorily carried out.


I may add that all fees and expenses in connexion with the matter must be paid by the Owners, or their Representatives, and should accordingly be charged by you to them.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. The Bathurst Trading Co., Ltd.,
Lloyd's Agents,
BATHURST,
River Gambia,
W. Africa.



© 2021

Lloyd's Register
Foundation

0101 2/2