

Are the fuses fitted in easily accessible positions

Yes

Are the fuses of standard dimensions

Yes

s/s "Iroquois"

N.Y.K. 4229

It is submitted that the New York Surveyors should be requested to state whether 2 or more cables are fitted carrying the 652 Amperes, as the area of one cable required by the Rules is not complied with as reported by them in their Elec. light report. Action in the meantime being deferred.

See N.Y.K. ltr. 27/6/27  
2 Cables

J.W.D.  
2/6/27

S.O. Lr N.Y.K. 9-6-27

009481-009492-0017

2 Cables. see N

DESCRIPTION OF CABLES.

S.W.G. diameter .586 square