

15 MAY 1939

2

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Kozyun' Manu Rpt. Smk No. 2460

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Nature of Survey 2nd S.S. No. 1 due 3,39.

The 2nd S.S. No. 1 has now been held, and the following repairs done due to wear and tear:-

Vessel placed in dry dock, bottom cleaned & coated.

9 shell plates - 45 bathous chain cable renewed, repairs

to a frame - tank top plate, & minor repairs effected.

It is submitted the vessel is worthy to remain as classed, with record of Survey 4,39 and notation of S.S. Smk No 1-39 as recommended.

100A1

4,39 Smk.

S.S. Smk No 1-39



© 2021

15.5.39
Lloyd's Register
Foundation

009505-009513-0165