

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

M. L. C. Delta

Report

Lon

No. 90437A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

D.B.S.

When due

7.26.

The Donkey Boiler became due for survey in July last.

In reply to notice sent the Owners now state that it is not necessary to retain the vessel's classification in the Register Book.

It is submitted that the vessel's class be withdrawn from the Register Book & three dots (...) inserted in lieu thereof indicating withdrawal of class at Owners request.

Withdraw class  
Insert...

27/9/26.

MS.

MS.



© 2021

Lloyd's Register  
Foundation

009514-009521-0050