

2m,11,38.

2 E

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME "MONTCALM". Rpt. Sou. No. 17353.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S-S-No~~

This Survey, due 4,39 now held
~~partly~~ ~~now~~
~~completed, and the following repairs carried out (due to~~):-

It is submitted the vessel is eligible to remain as classed, with
notation of BS 3,39, Starboard S3,39 as recommended.

Steam pipes to be tested at the Board of Trade Survey (approved.



© 2021

Lloyd's Register
Foundation 9.5.39.

009522-009526-0087