

NO. 464.

SPARE GEAR FOR SUPERHEATERS.

- 200 Jointing Rings.
- 50 Blank Plugs
- 30 Hex. Nuts
- 20 (4" centres) Dogs
- 2 Box Spanners.
- 2 Pyrometers with tubing
- 20 Spare elements
- 1 pair steel headers complete.



© 2021

Lloyd's Register  
Foundation

009522-009526-0128