


"TURNIA"

Before this case receives consideration IT IS SUBMITTED the Gdynia Surveyors be asked for their comments on the following:-

- 1) It is concluded the stern tubes are fitted with "CUTLESS" rubber bushes.
- ~~2) It is concluded the sea connections have been examined.~~
- 2X) It is not understood why full details of the cables, etc. have not been given on Report 13 covering electrical equipment. An amended report embodying this information should be forwarded.
- 3X) Have the Owners been asked whether they wish this Society to investigate the torsional vibration characteristics, and what is their reply?



*Emk.*

© 2020

16. 3. 49.

Lloyd's Register  
Foundation

009580-009589-0089