

Chief Ship Surveyor 13. 12. 17

Received from Chief Ship Surveyor

NAME Stl. Tw/S/S "HAKUSHIKA MARU". Rpt. Yka No. 2307

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

Survey

The Surveyors should be requested by cable to state the type of the stockless anchors fitted and at what machine these were tested.

Handwritten signature and date 13. 12. 17

also cable. Provisional freeboards confirmed cable when marked for classification

Handwritten initials and date 13/12/17

Handwritten date 13/12/17



© 2020

Lloyd's Register Foundation

009580-009589-0109

angles on ditto, No. of Plate, breadth and thickness

Vertical text on the right edge of the page, including 'unched', 'S. B.', 'mship', 'ook.', 'Dry Dock', 'o. of Deck', 'o. of Tier', 'and up of', 'ok. Beam', 'Inches Spacing in Ship', 'Inches in Ship', 'I h', '6', 'x', '5x', 'to', 'ful', 'x7/8', 'ngl', 'to', 'ang', '2'